



# Construction Photos

Feb 10, 2019 — March 2, 2019

**EB I-94 At Cooper Street Inspecting Beams Upon Delivery**





**EB I-94 At Cooper Street Exit Staging Beams**



**EB I-94 At Cooper Street Exit Staging Beams**





**EB I-94 At Cooper Street Exit Staging Beams**



**EB I-94 At Cooper Street Inspecting Beams Upon Delivery**





**EB I-94 West of Cooper Street Peat Excavation**



**EB I-94 West of Cooper Street Peat Excavation**





**EB I-94 West of Cooper Street Peat Excavation**



**EB I-94 West of RR Site Work Overview**





**EB I-94 East of RR Site Work Overview**



**EB I-94 West of RR Surveying Pier Caps**





**EB I-94 West of Grand River Site Work Overview**



**EB I-94 West of Grand River Site Work Overview**





**EB I-94 West of Grand River Prepping for Beam Placement**



**EB I-94 West of Grand River Placing Beams**





**EB I-94 West of Grand River Placing Beams**



**EB I-94 West of Grand River Placing Beams**





**EB I-94 West of Grand River Placing Beams**



**EB I-94 West of Grand River Placing Beams**

